

Broadband Connectivity Service (BBCS)

Version	14-27
Issue date	06.05.02.2021
Replaces version	14-25 or previous
Valid from	01.06.2021
Contract	Contract for Broadband Connectivity Services

Content

1	Recently tested BBCS equipment	3
1.1	ADSL, ADSL2+, VDSL G.vector, G.fast, XGS-Pon modems and routers	3
2	Disclaimer	5

1 Recently tested BBCS equipment

1.1 ADSL, ADSL2+, VDSL G.vector, G.fast, XGS-Pon modems and routers

The equipment mentioned in the list, is tested and approved by Swisscom (Switzerland) Ltd.
Swisscom recommends the End User to use the modems and routers tested and approved by Swisscom (Switzerland) Ltd.

Supplier	CPE	CPE-FW	Customer Premises Equipment				Technology					Model	Chipset			FW / BSP	
			CPE-DP	Fibre	POTS	ISDN	ADSL	ADSL2+	VDSL2 Vectoring	ADSL2+	VDSL2 Vectoring		G.fast	ADSL	VDSL2		G.fast
ADB	Centro Business V1	7.12.16	n/a		X	X	X		X			BDCM 6368	38q	38q	n/a	n/a	
ADB	Centro Business V1	7.12.18	n/a		X	X	X		X			BDCM 6368	38q	38q	n/a	n/a	
ADB	Centro Business V2	9.04.04 / 06 / 10	n/a		X	X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a	
ADB	Centro Business V2	9.50.02 / 9.50.04	n/a		X	X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a	
ADB	Centro Grande ADB	6.16.12 / 14	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a	
ADB	VV2220	4.1.0.0070	n/a		X	X	X					BDCM 63168	38q	38q	n/a	n/a	
ADB	SFP+ MAC_SX-1001 (aka XG-99S)	4.4.5.037 (currently supported only by Centro Business V2)	n/a	X								Cortina CA8271S rev.D	n/a	n/a	n/a	R1.0.0.0.0	
Arcadyan	Internet Box 3 (IB3)	11.03.50	n/a	X	X	X	X		X	X		BDCM 63158	46j2	46j2	46j2	5.02L06	
Arcadyan	Internet Box Standard (Starlite - SLT)	11.03.46	n/a		X	X	X		X			BDCM 63168	38q	38q	n/a	n/a	
Arnis	Centro Grande v1 Arnis	9.0.10h2d26	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a	
Arnis	Centro Grande v2 Arnis	9.0.10h2d26	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a	
Arnis	Centro Piccolo Arnis	9.0.10h2d26	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a	
Askey	Internet Box 2 (Stargate V2 - SG2)	11.03.50	n/a		X	X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a	
Askey	Internet Box Light (Starlink - SLK)	08.06.06	n/a		X	X	X		X			BDCM 63381	41g	41g	n/a	n/a	
AudioCode	Mediant-500L-MSBR	6.80A.335.005	n/a		X	X	X					IFTN VRX268	5731501	5781207	n/a	n/a	
AVM	Fritzbox 5530	07.25	n/a	X								MxL PRX	n/a	n/a	n/a	1.8.4	
AVM	Fritzbox 7490	113.07.21	1.100.136.43				X					IFTN VRX288	n/a	591407	n/a	n/a	
AVM	Fritzbox 7430	146.06.52	1.100.133.44				X					IFTN VRX288	n/a	578917	n/a	n/a	
AVM	Fritzbox 7560	149.06.69	1.148.135.11				X					A9-VRX3/518	n/a	790C17	n/a	n/a	
AVM	Fritzbox 7530	164.07.00	1.180.129.50				X					A9-VRX3/518	n/a	n/a	n/a	n/a	
AVM	Fritzbox 7530AX	256.07.25	n/a				X		X			BDCM 63178	n/a	46u	n/a	n/a	
AVM	Fritzbox 7582	156.07.01	n/a				X		X	X		BDCM 63138	42m	42m	43j2	n/a	
AVM	Fritzbox 7590	154.07.21	1.180.131.54				X		X			A9-VRX3/518	n/a	n/a	n/a	n/a	
Bintec-Elmeg	belf	10.1.27	n/a				X		X			IFTN VRX288	n/a	578917	n/a	n/a	
Bintec-Elmeg	RS353jv	10.1.27	n/a				X		X			IFTN VRX288	n/a	578917	n/a	n/a	

Supplier	CPE	CPE-FW	Customer Premises Equipment						Model	Chipset			FW / BSP			
			CPE-DP	Fibre	Technology			ADSL		DP	G.fast					
				XGS-PON (incl. BBF Certification)	ADSL	ADSL2+	VDSL2 Vectoring	ADSL	ADSL2+	VDSL2 Vectoring	G.fast	ADSL	VDSL2	G.fast	XGS-PON	
CIG	SFP+ MAC, XG-100S (aka XG-99S)	4.4.5.037 (currently supported only by Centro Business V3)	n/a	X								Cortina CA8271S rev.D	n/a	n/a	n/a	R1.0.0.0.0
Cisco	2921 HWIC VA	15.4(3)M4	n/a			X						BDCM 6368	n/a	38q	n/a	n/a
Cisco		15.7(3)M7	n/a			X						BDCM 6368	n/a	38q	n/a	n/a
Cisco	4300-NIM-VAB-A	17.2.1r	n/a			X			X			BDCM 63168	38q	38q	n/a	n/a
Cisco	886VA	15.2(4)M5	n/a					X	X			BDCM 6368	38r1	38r1	n/a	n/a
Cisco		15.5(3)M6a	n/a					X	X			BDCM 6368	38r1	38r1	n/a	n/a
Cisco	887VA	15.2(4)M5	n/a		X	X						BDCM 6368	38q	38q	n/a	n/a
Cisco		15.5(3)M6a	n/a		X	X						BDCM 6368	38q	38q	n/a	n/a
Cisco	C887VA-K9	15.3(3)M4	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco		15.4(3)M4	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco		15.5(3)M6a	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco		15.7(3)M6	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco	C897VA-K9	15.4(3)M4	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco		15.5(3)M6a	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco		15.7(3)M6	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
Cisco	C1113	16.9.5	n/a		X	X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a
Cisco		17.2.1r	n/a			X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a
Cisco	C1117	16.9.20180	n/a		X	X	X		X	X		BDCM 63168	38q	38q	n/a	n/a
Cisco	C1127 (baugleich zu C1117, 16.9.20180)	16.12.2	n/a		X	X	X		X	X		BDCM 63168	38q	38q	n/a	n/a
Huawei	SFP, Starplug	n/a (currently supported by Cisco C897, Starlite, Stargate V1)	n/a							X		MTIA 5321	n/a	n/a	8811r045	n/a
	HN8010Ts	V5R020C10S030	n/a	X								n/a	n/a	n/a	n/a	n/a
	HN8250Ts	V3R019C20S929T	n/a	X								HiSilicon SD5118V2	n/a	n/a	n/a	V300R019C20
Lancom	1781 series / 1783 series	09.10.0530	n/a		X	X	X					IFTN VRX268	572F11	577617	n/a	n/a
Nokia	XS-010X-Q	BBDR2004 (3FE49337AOCK57)	n/a	X								Cortina CA8271			n/a	n/a
oneAccess	1645 (one540, one700)	015.02 (5.2R1E4)	n/a			X			X			IFTN VRX268	n/a	574E17	n/a	n/a
oneAccess	1645 (One540) ADSL POTS	011.10 (5.2R1E2)	n/a			X						IFTN VRX268	571801	n/a	n/a	n/a
oneAccess	1645 (One540) ADSL ISDN	011.10 (5.2R1E2)	n/a						X			IFTN VRX268	571502	n/a	n/a	n/a
oneAccess	ONE425	5.2R1E4	n/a			X			X			IFTN VRX268	n/a	574E17	n/a	n/a
Sagemcom	Fast 5360	SG4D10001614 / SG4D10001448	n/a		X	X	X		X	X		BDCM 63138	43j2	43j2	43j2	n/a
Sagemcom	F@st 5688T (Sunrise Internet Box)	RC1 (02/06/2020)	n/a	X								BDCM 68580				5.02L07p1
Siligence	Internet Box Plus (Stargate V1 - SG)	11.03.46	n/a		X	X	X		X			BDCM 63168	38q	38q	n/a	n/a
Thomson	TG789vac	R10.5.8.J	n/a		X	X	X					BDCM 63168	38q	38q	n/a	n/a
Westermo	Falcon	WeOS 4.21	n/a		X	X		X	X			Vinax	n/a	9611305	n/a	n/a
ZyXEL	P-870H-51a (V1, V2)	1.12(VFJ.10)	n/a				X					BDCM 6368	n/a	38q	n/a	n/a
ZyXEL	P-870H-53a (V1, V2)	1.12(VFK.10)	n/a							X		BDCM 6368	n/a	38r1	n/a	n/a
ZyXEL	P-870HN-51b (V1, V2)	1.12(VFH.10)	n/a		X	X	X					BDCM 6368	38q	38q	n/a	n/a
ZyXEL	P-870HN-53b (V1, V2)	1.12(VFL.10)	n/a						X	X		BDCM 6368	38r1	38r1	n/a	n/a
ZyXEL	SBG 3300N (3500N, 3600N, VMG1312)	V100AAIV1C0 (V100AATP1C0, V100AAZN3C0, V100AAJZ6C1)	n/a				X					BDCM 63168	n/a	38q	n/a	n/a
ZyXEL	SBG 3300N-I (3500N-I)	V100AAIX1C0 (V100AATQ1C0)	n/a						X			BDCM 63168	n/a	38r1	n/a	n/a
ZyXEL	SBG5500-A	V1.10(AAZT.0)C0	n/a				X		X			BDCM 63138	n/a	42m	n/a	n/a
ZyXEL	XMG3927-B50A	ABMT0C	n/a				X		X	X		BDCM 63138	n/a	43j2	43j2	n/a
ZyXEL	AX7501-B0	V5.15(ABWW.0)	n/a	X								BDCM 68580	n/a	n/a	n/a	5.02L07

2 Disclaimer

- The CPE (modem or router) is owned by the End User or (I)SP and is under the service responsibility of the End User or (I)SP.
- This document is subject to alterations. Swisscom (Switzerland) Ltd. is not responsible for CPE changes, which are not tested separately.
- In case of an End User in-house problem, Swisscom (Switzerland) Ltd. will test the line synchronisation with a Swisscom CPE as reference. It is possible that the CPE from another manufacturer does not synchronise due to longer distance between the Central Office and the End User.