

Broadband Connectivity Services

Version	14-39
Issue date	18.02.2026
Replaces version	14-38 or previous
Valid from	01.03.2026
Contract	Contract for Broadband Connectivity Services

Content

1	Recently tested BBCS equipment	3
1.1	ADSL2+, VDSL G.vector, G.fast, XGS-Pon modems and routers	3
2	Disclaimer	8

1 Recently tested BBCS equipment

1.1 ADSL2+, VDSL G.vector, G.fast, XGS-Pon modems and routers

The equipment mentioned in the list, is tested and approved by Swisscom (Switzerland) Ltd.

Swisscom recommends the End User to use the modems and routers tested and approved by Swisscom (Switzerland) Ltd.

Supplier	CPE	CPE			Technology				
		CPE-FW	CPE-DP	Fibre	XGS-PON	ADSL2+	VDSL2 Vectoring	ISDN	g.fast
ADB	Centro Business V1	7.12.20	n/a	-	X	X	-	X	-
ADB	Centro Business V2	9.52.20	n/a	X	X	X		X	X
ADB	ST6840 VTX (Centro Business V2)	VTX1000008	n/a		X	X		X	X
ADB	Centro Business V3	10.04.10	n/a	X	X	X			X
ADB	VV2220	4.1.0.0070	n/a		X	X			
ADB	VD6722	E.E.10.02	n/a		X	X		X	
ADB	SFP+ MAC, SX-1001 (aka XG-99S - 105AF7)	4.4.5.051 (currently supported only by Centro Business V2)	n/a	X					
Arcadyan	Internet Box 3 (IB3)	15.10.44	n/a	X	X	X		X	X
Arcadyan	Internet Box 4 (IB4)	15.10.44	n/a	X					
Arcadyan	Internet Box 5 (IB5)	15.10.44	n/a	X	X	X		X	X
Arcadyan	Internet Box 5 Pro (IB5Pro)	15.10.44	n/a	X					
Arcadyan	Internet Box Standard (Starlite - SLT)	11.06.08	n/a		X	X		X	
Askey	Internet Box 2 (Stargate V2 - SG2)	14.30.02	n/a		X	X		X	X
Askey	Internet Box Light (Starlink - SLK)	08.06.10	n/a		X	X		X	
AudioCode	Mediant-500L-MSBR	6.80A.335.005	n/a		X	X			

Supplier	CPE			Technology					
	CPE	CPE-FW	CPE-DP	Fibre XGS-PON	POTS		ISDN		g.fast
					ADSL2+	VDSL2 Vectoring	ADSL2+	VDSL2 Vectoring	
Fritz! GmbH	Fritzbox 5530	07.29	n/a	X					
Fritz! GmbH	Fritzbox 5590	07.50	n/a	X					
Fritz! GmbH	Fritzbox 5690Pro	07.62	1.196.9.40		X				
Fritz! GmbH	Fritzbox 5690XGS	08.00	n/a	X					
Fritz! GmbH	Fritzbox 7490	113.07.29	1.100.136.43		X				
Fritz! GmbH	Fritzbox 7560	149.06.69	1.148.135.11		X				
Fritz! GmbH	Fritzbox 7530	164.07.00	1.180.129.50		X		X		
Fritz! GmbH	Fritzbox 7530AX	256.07.25	n/a		X		X		
Fritz! GmbH	Fritzbox 7582	156.07.01	n/a		X		X	X	
Fritz! GmbH	Fritzbox 7583	167.08.20	1.196.9.60		X		X	X	
Fritz! GmbH	Fritzbox 7590	154.07.29	1.180.131.76		X		X		
Fritz! GmbH	Fritzbox 7590AX (&V2)	259.07.31	1.196.7.44		X		X		
Fritz! GmbH	FRITZ!Box 7630	304.08.21	1.180.3.55		X		X		
Fritz! GmbH	FRITZ!Box 7632	303.08.10	1.196.9.60		X		X	X	
Fritz! GmbH	Fritzbox 7682	286.08.03	1.196.9.54		X		X	(X)	
Fritz! GmbH	Fritzbox 7690	285.07.61	1.196.9.40		X		X		
Bintec-Elmeg	beIP	10.1.27	n/a		X		X		
Bintec-Elmeg	RS353jv	10.1.27	n/a		X		X		
CIG	SFP+ MAC, XG-100S (aka XG-99S - 2083F8)	4.4.5.051 (currently supported only by Centro Business V3)		X					
CIG	SFP+ MAC, XS-010S-Q (Nokia)	3FE49336AOCK59 supported with Centro Business V3		X					
CIG	SFP+ MAC, XG-100S (ADB)	4.4.5.049 (currently supported only by ADB VD6723 or VD6722)		X					
CIG	SFP+ MAC, ALL-BM410 (Allnet)	4.4.20.043 (currently supported only by Mikrotik)		X					
CIG	SFP+ MAC, SFP-XGSPON-1 (Lancom)	4.4.20.025 supported with Lancom 2100EF		X					

Supplier	CPE			Technology					
	CPE	CPE-FW	CPE-DP	Fibre XGS-PON	POTS		ISDN		g.fast
					ADSL2+	VDSL2 Vectoring	ADSL2+	VDSL2 Vectoring	
Cisco	2921 HWIC VA	15.7(3)M7	n/a			X			
Cisco	NIM-VAB-A	17.6.4 (tested with ISR4331)	n/a			X		X	
Cisco	C887VA-K9	15.7(3)M6	n/a		X	X			
Cisco	C897VA-K9	15.7(3)M6	n/a		X	X			
Cisco	C927-4P	15.9-3-M1	n/a			X		X	
Cisco	C1113	17.6.4	n/a			X		X	X
Cisco		17.9.4a	n/a			X		X	X
Cisco	C1117	16.9.20180	n/a		X	X		X	
Cisco	C1127 (baugleich zu C1117, 16.9.20180)	16.12.2	n/a		X	X		X	
Genexis	FiberTwist XGS2110-2.5	InterOS E-5.2.0-R	7.3.267.200	X					
Genexis	FiberTwist XGS2110; FiberTwist XGS2310B	InterOS E-5.2.0-R	7.3.267.200	X					
Huawei	SFP, Starplug	n/a (currently supported by Cisco C897, Starlite, Stargate V1)	n/a						X
Huawei	HN8010Ts	V5R020C10S030	n/a	X					
Huawei	EN8010Ts-20	V5R022C00S201	n/a	X					
Huawei	HN8250Ts	V3R019C20S929T	n/a	X					
Huawei	EN8245X6s-8N	V5R021C10S244	n/a	X					
Huawei	EN8255X6s-8X	V5R023C00S125	n/a	X					
Huawei	OptiXstar V581s	V5R025C00S101	n/a	X					

CPE				Technology					
Supplier	CPE	CPE-FW	CPE-DP	Fibre XGS-PON	POTS		ISDN		g.fast
					ADSL2+	VDSL2 Vectoring	ADSL2+	VDSL2 Vectoring	
LANCOM	1793VAW	10.50.0331	n/a		X	X		X	
LANCOM	1926VAG & 1926VAG-5G	10.50.0331	n/a		X	X		X	(X)
LANCOM	1800VA, 1800VAW, 1800VAW-4G, 1800VA-4G, 1800VA-5G, 1803VA, 1803VAW, 1803VA-4G, 1803VA-5G, R903, 1800VAW-5G, 1803VAW-5G	10.80.0448	na			X		X	
LANCOM	1936VAG, 1936VAG-5G	10.92.0167	na		X	X		X	(X)
LANCOM	1781 series / 1783 series	09.10.0530	n/a		X	X			
Nokia	XS-010X-Q	3FE49337BOCK28	n/a	X					
Nokia	XS-010X-R	3TN00669AOCK75	n/a	X					
Nokia	XS-010G-Q	3FE49337BOCK28	n/a	X					
Nokia	XS-2426G-B	3FE49544HJML57	n/a	X					
Nokia	XS-2426X-A	3FE49940HJML57	n/a	X					
Nokia	XS-2437X-A	3TN00988HJMK92	n/a	X					
MET	SFP V5311-T-R (aka MT5311/META)	1_62_8570	n/a		X	X			
MET	SFP SC-G5321 (aka MT5321/MTIA)	8814r044	n/a						X
oneAccess	1645 (one540, one700)	015.02 (5.2R1E4)	n/a			X		X	
oneAccess	1645 (One540) ADSL POTS	011.10 (5.2R1E2)	n/a		X				
oneAccess	1645 (One540) ADSL ISDN	011.10 (5.2R1E2)	n/a				X		
oneAccess	ONE425	5.2R1E4	n/a			X		X	
Sagemcom	Fast 5360 (SIB 1)	SG4D10001810 / SG4D10001910	n/a		X	X		X	X
Sagemcom	Fast 5688T (SIB 2)	02.136	n/a	X					
Sagemcom	Fast 5685 (MERC3 / MV3)	3.7.5	n/a	X					

Supplier	CPE			Technology					
	CPE	CPE-FW	CPE-DP	Fibre XGS-PON	POTS		ISDN		g.fast
					ADSL2+	VDSL2 Vectoring	ADSL2+	VDSL2 Vectoring	
Siligence	Internet Box Plus (Stargate V1 - SG)	11.06.06	n/a		X	X		X	
Thomson	TG789vac	R10.5.8J	n/a		X	X			
TPLink	VB400v	FW_0.1.0_3.0.0v6123_build251207	n/a		X	X			X
TPLink	VX800v	FW_0.8.0_3.0.0v603c0_build250902	n/a		X	X			X
Westermo	Falcon	WeOS 4.21	n/a		X		X		
ZyXEL	SBG 3300N (3500N, 3600N, VMG1312)	V100AAIV1C0 (V100AATP1C0, V100AAZN3C0, V100AAJZ6C1)	n/a			X			
ZyXEL	PE5301-01	V5.63(ACOJ.1)C0	n/a	X					
ZyXEL	XMG3927-B50A	ABMT0C	n/a			X	X	X	
ZyXEL	GM4100-B0	5.18(ACCL.x)C0 (generic)	n/a			X	X	X	
		5.18(ACKJ.3)C0 (Sunrise)	n/a			X	X	X	
ZyXEL	PM7300-T0	V5.42(ABYY1.3)C0	n/a	X					
ZyXEL	PM7500-00	V5.61(ACKK.0.1)b2	n/a	X					
ZyXEL	AX7501-B0	V5.15(ABPC.0)	n/a	X					
ZyXEL	AX7501-B0	V5.15(ABWW.2) (Sunrise)	n/a	X					
ZyXEL	AX7501-B1	V5.15(ABPC.xy)	n/a	X					
ZyXEL	AX7501-B1	V5.17(ABWW.5) (Sunrise) & SFP PM7000-01	n/a	X					

based on 3.07 Changes are marked yellowish

End of Supplier Support

(X) accepted with restrictions

2 Disclaimer

- The CPE (modem or router) is owned by the End User or (I)SP and is under the service responsibility of the End User or (I)SP.
- This document is subject to alterations. Swisscom (Switzerland) Ltd. is not responsible for CPE changes, which are not tested separately.
- In case of an End User in-house problem, Swisscom (Switzerland) Ltd. will test the line synchronization with a Swisscom CPE as reference. It is possible that the CPE from another manufacturer does not synchronize due to longer distance between the Central Office and the End User.
- Restrictions usually means that there is a slight downgrade in performance. More details can be obtained from the supplier.